Support Group Application Note

Number: 019 Issue: 1.00 Author: PFD



# **DFS** Error Messages

There have been a number of revisions of the DFS firmware and software fitted to the various 8 bit machine. The error messages have remained consistent throughout the revisions and this application note lists the fault numbers with a description.

Applicable Hardware:

BBC Model B BBC Model B + BBC Master 128 Related Application Notes:

Copyright © Acorn Computers Limited 1992

Every effort has been made to ensure that the information in this leaflet is true and correct at the time of printing. However, the products described in this leaflet are subject to continuous development and improvements and Acorn Computers Limited reserves the right to change its specifications at any time. Acorn Computers Limited cannot accept liability for any loss or damage arising from the use of any information or particulars in this leaflet. ACORN, ECONET and ARCHIMEDES are trademarks of Acorn Computers Limited.

Support Group
Acorn Computers Limited
Acorn House
Vision Park
Histon
Cambridge CB4 4AE

## Error 08 (clock error)

During a disc read operation a clock bit was missing.

### Error **0A** (late DMA)

During a disc transfer the processor did not respond fast enough, most likely due to a faulty disc interface card.

## **Error 0C** (ID Field CRC error)

The cyclic redundancy check derived from the data read back differed from that stored on the disc.

# Error 0E (data CRC error)

The cyclic redundancy check derived form the data read back differed from that stored on the disc during a disc read.

## **Error 10** (drive not ready)

During a transfer the disc stopped rotating. Often caused by a badly inserted disc.

## Error 14 (track zero not found)

Controller failed to find track zero. Often an unformatted disc.

### **Error18** (sector not found)

Controller failed to find required sector. Either a corrupted or an unformatted disc.